



## DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street  
Westminster, Maryland 21157

## WESTMINSTER PLANNING DISTRICT

## FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR-1037

NEGATIVE FILE NUMBER:

UTM REFERENCES:

Zone/Easting/Northing

U.S.G.S. QUAD. MAP: Lineboro

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: vacant

ORIGINAL USE: General Store / Hotel

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent ( ) Good ( )

Fair (X) Poor ( )

THEME: Commercial

STYLE: vernacular

DATE BUILT:

COUNTY: CARROLL

TOWN: LINEBORO

LOCATION: 4217 Main Street (mo 80)

COMMON NAME: Lineboro General Store

FUNCTIONAL TYPE: Store

OWNER: Dana Lunceford 681/543  
ADDRESS: 4217 Main Street  
Lineboro Md 21088

ACCESSIBILITY TO PUBLIC:

Yes ( ) No ( ) Restricted ( )

LEVEL OF SIGNIFICANCE:

Local ( ) State ( ) National ( )

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone (X) Brick ( ) Concrete ( ) Concrete Block ( )
2. Wall Structure
  - A. Wood: Log ( ) Post and Beam ( ) Balloon (X)
  - B. Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
  - C. Iron ( ) D. Steel ( ) E. Other
3. Wall Covering: Weatherboard (X) German Siding ( ) Board and Batten ( )  
Wood Shingle ( ) Shiplap ( ) Novelty ( ) Stucco ( ) Sheet Metal ( )  
Aluminum ( ) Asphalt Shingle ( ) Brick Veneer ( ) Stone Veneer ( )  
Bonding Pattern: Other:
4. Roof Structure
  - A. Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )
  - B. Other:
5. Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal (X)  
Built Up ( ) Rolled ( ) Tile ( ) Other:
6. Engineering Structure:
7. Other:

Appendages: Porches (X) Towers ( ) Cupolas ( ) Dormers ( ) Chimneys ( ) Sheds ( )  
Ells ( ) Wings ( ) Other:Roof Style: Gable (X) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( )  
With False Front ( ) Other: front gable

Number of Stories: 3

Number of Bays: 5 X 4

Approximate Dimensions:

Entrance Location: 2 entrances

THREAT TO STRUCTURE:

No Threat (X) Zoning ( ) Roads ( )  
Development ( ) Deterioration ( )  
Alteration ( ) Other:

LOCAL ATTITUDES:

Positive ( ) Negative ( )  
Mixed ( ) Other:

## ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

unusual commercial structure - five-bay main facade - 3 bays offset to north  
gable front with unornamented pediment  
full-length, one-story porch  
northern 3 bays of 1st story has plate glass storefront

## RELATED STRUCTURES: (Describe)

## STATEMENT OF SIGNIFICANCE:

P.O. was here with General Store

## REFERENCES:

1862 Martenet's Map:  
1877 LG & S Atlas:

## SURROUNDING ENVIRONMENT:

Open Lane ( ) Woodland ( ) Scattered Buildings ( )  
Moderately Built Up ( ) Densely-Built Up ( )  
Residential ( ) Commercial ( )  
Agricultural ( ) Industrial ( )  
Roadside Strip Development ( )  
Other: Village

## RECORDED BY:


Joe Getty

## ORGANIZATION:

Carroll Co. Dept. of Planning

## DATE RECORDED:

February 1985



LINEBORO, MD. - PA.

QUADRANGLE

7.5 minute series



1. CARR-1037
2. Carroll County, Maryland
3. Joe Getty
4. February 1985
5. Md. Historical Trust, Annapolis, Md.
6. west elevation